

PRESALTING ROUTES – 2016/17

ROUTE: INDUSTRIAL

DEPOT: NEW VALE

NOTE: ENSURE THAT ALL ROUNDABOUTS ON ROUTE ARE COMPLETELY GRITTED.

1. NOT SALTING: Proceed from Central Depot turn left to roundabout, take 1st exit to Heads of the Valleys Road at HoV roundabout take 2nd exit to Ebbw Vale roundabout take 1st exit to Ebbw Vale, Proceed to New Roundabout take 2nd exit A 4047 (Morrison).
2. START SALTING: On entering roundabout leave at 3rd exit. Proceed around all main routes on Industrial Estate. Exit site on to HoV but return back into Rassau Industrial Estate (to grit entry road from HoV) to Beaufort Wells roundabout, return and exit site on to HoV once again, go into Crown Avenue Industrial Site, proceed around all main routes on Industrial Estate. Exit site at Crown Avenue, turn right and go to Cemetery, turn vehicle and return down Crown Avenue to junction with St Luke's Road. STOP SALTING.
3. NOT SALTING: Turn right at junction, down St Luke's Road to Crown roundabout A4048.
4. START SALTING: Proceed along Merthyr Road towards Rhymney Bridge and go to Caerphilly CBC Boundary. STOP SALTING.
5. NOT SALTING: Return along Merthyr Road to entrance of Tafarnaubach Industrial Estate.
6. START SALTING: Proceed around Tafarnaubach Industrial Estate after completing site, return to site entrance. STOP SALTING.
7. NOT SALTING: Proceed to A4046 to Traffic Lights – New Learning Zone
8. START SALTING: Turn left into approach road and junction turn right towards New Hospital turn right into Hospital car park complete Mini roundabout return to through road turn right at junction Festival Drive, turn right at Traffic lights turn right proceed along A4046 to next set of Traffic Lights, turn right into approach road at Junction turn left, proceed through New Learning Zone to roundabout on steelworks road, complete roundabout return through New learning Zone Exit Via 1st Right (approach Road) at Traffic lights turn left, Proceed along A4046 to next set of Traffic Lights turn right Festival Drive: proceed along Festival Drive to Garden Festival roundabout, over roundabout along Augusta Street, left down road to roundabout at Baldwin, Victoria and Festival Houses. Turn left at roundabout into Glan Ebbw Terrace. Turn left into unnamed access road to train station car park, turn right into car park. Salt car park, turn left on to A4046 at new junction to Festival roundabout, turn left and proceed to Garden Festival shopping area roundabout. STOP SALTING.
9. NOT SALTING: Return to junction Hall Street Industrial Site, turn left.
10. START SALTING: Proceed through Site to end. STOP SALTING.

11. NOT SALTING: Return to Garden Festival roundabout.
12. START SALTING: Proceed along A4046 to Aberbeeg roundabout.
13. **Mini – Gritter (Foreman) - Aberbeeg Square**
14. **START SALTING: Proceed along unnamed road to Railway Bridge, proceed under Railway Bridge.**
15. **SALTING: Return along unnamed road to junction of A4046.**
16. Not Salting – Industrial Gritter - Take 3rd left A467 proceed along A467 to Traffic Lights at Llanhilleth Industrial Estate.
17. START SALTING: Turn left at lights, 1st right into Industrial Estate, complete Industrial Estate on leaving Industrial Estate, turn right along unnamed road to junction by Llanhilleth Institute. STOP SALTING.
18. NOT SALTING: Turn and return to Traffic Lights on A467, turn right at lights, proceed along A467.
19. START SALTING: Turn into Glandwr Industrial Estate, proceed to grit whole Estate, exit site on to Commercial Road. STOP SALTING.
20. NOT SALTING: At junction on Commercial Road turn left proceed to Aberbeeg roundabout, 2nd exit A4046 to roundabout (Old Colliery Site), Cwm.
21. START SALTING: Proceed along Marine Street (include Marine Street Industrial Site), Turn left at end of Marine street/Mill terrace into Canning Street proceed along Canning Street to end turn at Cwm Welfare Ground / Primary School return to junction with Marine Street turn left Mill Terrace / Station Terrace to junction of new By-Pass. STOP SALTING
22. NOT SALTING: Proceed to junction A4046/Silent Valley Tip, turn right.
23. **START SALTING: Proceed up Cemetery Road to entrance of Silent Valley Waste Services, Open gates proceed along access road to Waste Transfer Station. STOP SALTING.**
24. **NOT SALTING: Return to entrance gates, lock gates and return to A.4046.**
25. NOT SALTING: Turn right and Proceed to New Roundabout on A4046 (Bottom of Park Hotel)
26. START SALTING: At Roundabout take 2nd exit (New By-pass) proceed to next roundabout take 1st exit (The Works) proceed along A4281 to junction steelworks road. STOP SALTING
27. NOT SALTING: Proceed to General Offices turn right Cwm Draw Ind. Estate.

28. START SALTING: Proceed through Industrial Estate exit on to Newtown roundabout take 2nd exit Newtown, up Newtown Hill, Brynmawr road and Bus Bay. STOP SALTING.

29. Return to New Vale Depot to fill with Salt and then return to Central Depot.