

## PRESALTING ROUTES – 2016/17

### ROUTE: TREDEGAR

### DEPOT: NEW VALE

**NOTE:** ENSURE THAT ALL ROUNDABOUTS ON ROUTE ARE COMPLETELY GRITTED.

1. NOT SALTING: Proceed from Central Depot turn left to roundabout, take 1<sup>st</sup> exit to Heads of the Valleys Road at HoV roundabout take 2<sup>nd</sup> exit to Ebbw Vale.
2. START SALTING: Ebbw Vale roundabout 1<sup>st</sup> exit proceed along A4046 to Ebbw Vale, at New Roundabout take 2<sup>nd</sup> exit A4047 and proceed along A4047 to junction Dukestown Road, along Dukestown Road, then left to Sirhowy Bridge roundabout, left up Beaufort Road, left along Dukestown Road, along St Luke's Road to Crown roundabout A4048, North along A4048, over HoV roundabout to Quarryman's Arms, Trefil – return and proceed to Trefil Village, turn left to Railway Terrace, proceed up to and including Railway Terrace to gates of Concrete Works. STOP SALTING.
3. NOT SALTING: Return down Trefil Road to entrance of Waundeg Estate near Mountain Air Pub.
4. START SALTING: Proceed around Waundeg bus route emerging on to main road near and opposite Bush Bach. STOP SALTING.
5. NOT SALTING: Return to Crown roundabout A4048.
6. START SALTING: Proceed along A4048 to Caerphilly CBC's boundary near Pochin Houses. STOP SALTING.
7. NOT SALTING: Return to Heathfield Bridge roundabout.
8. START SALTING: Proceed through Pochin Crescent, Vale Terrace to Park Place roundabout. STOP SALTING.
9. NOT SALTING: Return to Pochin Crescent.
10. START SALTING: Turn Left on to Glyn Terrace (Bus Route) at crossroads Vale View / Peacehaven Proceed through Peacehaven to Roundabout, complete roundabout and return to Vale View, turn right along Vale View turn left Rhyd Terrace travel along Rhyd Terrace, Whitworth Terrace, and continue along Poplar Road to junction Vale Terrace. STOP SALTING.
11. NOT SALTING: Proceed to Park Place roundabout A4048.
12. START SALTING: Proceed along Promenade, Morgan Street, Castle Street, left along Park Row, up Parkhill, to Caerphilly CBC's boundary on Rhymney Road at Heathcock. STOP SALTING.
13. NOT SALTING: Return to junction Attlee Way/Cefn Golau.

14. **START SALTING:** Proceed along Attlee Way to junction Queen Victoria Street, left up Gainsborough Road, 2nd left Walter Conway Avenue, left Gainsborough Road to junction Attlee Way, left along Attlee Way along Queen Victoria Street, left through Commercial Street to lights, turn right along New Road at side of Tredegar Bus Station and Car Park, to junction Commercial Street, along Commercial Street again to lights, straight over lights and go to **Roundabout on By – Pass. Return to Left Turn for Vitec Centre, Turn in proceed to Turning Area. STOP SALTING. Return Junction with Main Road then turn left to Traffic Lights.**
15. **NOT SALTING: Return to Junction with Main Road and turn left to Traffic Lights,**
16. **START SALTING:** Turn Left into and go along Church Street, through “bus only” lane into Charles Street, along Charles Street to Ashvale, go right to A4048 roundabout and return to Ashvale, along Ashvale, Merthyr Road to Crown roundabout return along Merthyr Road right up Brynbach Street, left Pembroke Street, North Avenue to Sycamore Avenue, along Sycamore Avenue, right into Gwent Way Industrial area. **STOP SALTING.**
17. **NOT SALTING:** Return to junction Sycamore Avenue/Stockton Way turn right at junction.
18. **START SALTING:** Along Stockton Way turn right into Gelli Road, right Stocktonville through Gwent Way Estate to junction Stockton Way, right along Stockton Way to junction Church Street. **STOP SALTING.**
19. **NOT SALTING:** Return to junction Stockton Way/Gelli Road.
20. **START SALTING:** At the junction of Gelli Road/Stockton Way proceed along Stockton Way to Traffic Lights turn right proceed through Bus Bay, left on to Stockton Way turn left Gelli Road, Earl Street, Union Street to junction Queen Victoria Street. **STOP SALTING.**
21. **NOT SALTING:** Proceed to Promenade near Park Place roundabout A4048.
22. **START SALTING: Go along Promenade towards School, including bus bays, up Stable Lane, (If Gates Open) Turn Left into Tredegar Comprehensive School proceed to roundabout Return to Stable Lane turn Left up Stable Lane along Park Row, down Market Street up Castle Street, right into Duke Street, right lower Coronation Street (past Fire Station), Iron Street, right to clock roundabout, return down Iron Street (passing Police Station), right Iron Row, left Bridge Street Industrial area. STOP SALTING**
23. **NOT SALTING:** Proceed to junction Park Place, Vale Terrace, turn left.
24. **START SALTING:** Proceed along Park Place, up Georgetown Hill, left Thomas Ellis Way, along Thomas Ellis Way to junction Beaufort Road, left down Beaufort Road, right along Chartist Way, right Ysguborwen, right Rhoslan to junction Beaufort Road. **STOP SALTING.**
25. **NOT SALTING:** Proceed to Beaufort Road to Bleak House.

26. START SALTING: Turn left into Rhoslan to junction Ysguborwen. STOP SALTING.
27. NOT SALTING: Proceed to junction Ysguborwen / Chartist Way.
28. START SALTING: Proceed down Chartist Way to junction Dukestown Road. STOP SALTING.
29. NOT SALTING: Proceed to junction Glanhowy Street/St Luke's Road, turn left.
30. START SALTING: Proceed along Glanhowy Street, Scwrfa Road to junction Dukestown Road. STOP SALTING.
31. NOT SALTING: Proceed to Waun-y-Pound Industrial Estate (Alfred Teeves), turn right.
32. START SALTING: Turn right proceed past Alfred Teeves turn left, proceed to roundabout, complete roundabout take 4<sup>th</sup> exit return past Alfred Teeves to junction A4047 turn right along A4047 turn right at Robert Price's proceed to roundabout take 1<sup>st</sup> left proceed to New salt Barn turn and return to roundabout take 1<sup>st</sup> left New Vale Depot – Fill with Salt.
33. NOT SALTING: Return to Central Depot Via H.O.V. Road.
34. START SALTING (Mini Gritter) - Turn off Poplar Road into Fields Road, turn left along Oakfield road, proceed to school entrance. STOP SALTING